

WHORTON LOG HOUSE

AL-II-A-062

Dolly Road, north of Route 40, Flintstone
ca. 1890

The Whorton House is a two story, two bay wide, rectangular structure. Logs in the house are laid with dove tail notching while the chinking is cement. The Whorton Log House is typical of the type of housing utilized by the less affluent citizens of Allegany County throughout the 19th century.

MARYLAND HISTORICAL TRUST

0101395604
AL-II-A-062

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Whorton Log House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Dolly Road, north of Route 40

CITY, TOWN

Flintstone

☒ VICINITY OF

CONGRESSIONAL DISTRICT

Sixth

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO

PRESENT USE

☐ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☒ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER**4 OWNER OF PROPERTY**

NAME

Della Whorton

Telephone #: 78-2454

STREET & NUMBER

P.O.

CITY, TOWN

Flintstone

☒ VICINITY OF

STATE, zip code

Maryland

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Allegany County Courthouse

Liber #: 213

Folio #: 488

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland,

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION**CONDITION**

☐ EXCELLENT
☒ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☒ UNALTERED
☐ ALTERED

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Whorton Log House on the east side of Dolly Road, approximately 200 yards north of Route 40 near Flintstone, Allegany County.

The Whorton Log House is a two story, two bay wide, rectangular block. A single story rectangular, frame addition abuts the main block on the north side. Logs in the house are laid with dovetail notching while the chinking is cement. The house rests on a low foundation constructed of log joists resting on stone pilings. Windows in the house are one over one lights with plain trim. The main entrance, which is located on the south side of the house, is covered by a three bay end porch with a shed roof. A second porch is found on the east side of the frame addition. The roof of the Whorton House is gabled with a soffit and is covered with tin. Two cement block chimneys are located at the outside ends of the building.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW				
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION		
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE		
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE		
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN		
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER		
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION		
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)		
		<input type="checkbox"/> INVENTION				

SPECIFIC DATES ca. 1890

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Log Cabin remained a popular form of housing in Allegany County until the present century; and Whorton Log House is an excellent example of this type. The structures were inexpensive to build, easy to construct and extremely sturdy. In the 1890 decade, numerous log structures were built in the county by its less wealthy inhabitants, as subsistence type farms. Soon after their construction, many of these buildings were generally covered with board and batten; however, this example retains its exposed log surface.

An interesting group of these log houses can be found in the Eastern portion of Allegany County. The buildings are generally two stories high and two or three bays wide with some additions to accommodate a growing family's needs. The Whorton Log House is a good example of such a structure and is similar in construction to the E.V. Sportsman's Club Log House, the Carder Log House and others located nearby.

The house is structurally near its original appearance and remains a cultural and architectural reminder of a way of life once found in Allegany County.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Cumberland, Maryland

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 24 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

John Nelson, Joan Baldwin & Steve Beale

ORGANIZATION

Allegany County Historic Sites Survey

DATE

11/8/76

STREET & NUMBER

507 National Highway

TELEPHONE

777-8991

CITY OR TOWN

LaVale,

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTORY NO. AL-II-A-062

213/488

DATE: 10/11/78

24 A.

REMODELING: Drastic, moderate, minorNAME OF PROPERTY: Wharton
Log HouseLOCATION OF PROPERTY: Dolly Rd. north of Rt. 40, FlintstoneDIRECTION DWELLING FACES: SouthNAME OF OWNER: Dalla Wharton Wharton 478-2454

ADDRESS: _____

FlintstoneSTORIES: 1() 2(☒) 3() 4() 5() 6() BAYS: 1() 2(☒) 3() 4() 5() 6() 7() ()WINGS, ADDITIONS: ons/rstDwelling Shape: (square, cross, rectangular)

WALL CONSTRUCTION:

- () FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
() BRICK: Bond type- common, English, Flemish. Sketch variants.
() STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
(☒) LOG dove tail notching/wood + cement chinking
() Other: Coverings

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS _____

FOUNDATIONS: HIGH, LOW, BRICK, STONE Log joints on stone pilings

WATER TABLE: NONE, PLAIN, BEVELED, MOULDED BRICK

WINDOWS, TRIM, SHUTTERS: 1/1(☒) 2/2() 6/6() 9/6() 9/9() other()
pegged () nailed () wide () narrow () mitred () pediment ()

ENTRANCE, DOORS: LOCATION: _____

HARDWARE: original() replaced()
FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN
Paneled, Verticle, Horizontal BoardsCORNICE, BARGE, EAVES: (crown, fascia, soffit, bed)
original() replaced() Rafter Ends, Modillions, Dentils, Frieze, Architrave
on additionROOF: GABLE FRONT, GABLE FLANK, HIP, SHED, MANSARD, GAMBREL, FLAT, FORMERS #
MATERIAL: wood shingles, slate, tin, asphalt original() replaced()PORCHES: SHAPE OF ROOF - shed(☒) hip() gable() replaced
cement blockCHIMNEYS: NUMBER 1 BRICK() STONE() CORBELED() original() replaced()
LOCATION: Flush end() Inside end() Outside end(☒) Central() Interior()

ARCHES: Door and window: Keystone, Flat, Segmental, Semicircular

COMMENTS:

Use - CabinSignificance - ArchDate Constructed - 1890's?Condition - good

AI-II-A-062
Wanton Log House
Dolly Rd.

USGS - Flintstone Quad

1:24,000

1950

PENNSYLVANIA
MARYLAND

AI-II-A-062

AI-II-A-060

AI-II-A-048

AI-II-A-051

AI-II-A-052

AI-II-A-046

AI-II-A-056

AI-II-A-050

AI-II-A-047

AI-II-A-001

AI-II-A-049

AI-II-A-045

AI-II-A-058

AI-II-A-044

AI-II-A-057

AI-II-A-043

AI-II-A-064

AI-II-A-042

AI-II-A-055

AI-II-A-041

AI-II-A-040

AI-II-A-039

AI-II-A-038

AI-II-A-054

AI-II-A-059

AI-II-A-067

AI-II-A-063

AI-II-A-073

AI-II-A-005 & 065

AI-II-A-061



AI-II-A-062

Warton Log House

1/2 M. North of Rt 40 - Flintstone

John E. Nelson

10/13/76

Northeast



A1-11-A-062

Warten, Hwy 100SS

$\frac{1}{2}$ m. N. of Rt. 40, Flintstone

John E. Nelson

10/13/76

Southwest